Work Orde					*100440*									Page 1		
Revision ID: Item Name:	D3916-5 Light Rib 4/30/13 4/30/13	Start (Qty: 10.00 Qty: 10.00		10* 10*	Accept	C	900 ust Item I ustomer:	٠	100) *	Setup Sta	! /	S1* S2*		
Approvals:	Process	s Plan: M	 165	Date: /3-	54-27	Tooling:		Da	nte:		1	Run Sta	rt *N	R1*		
•						SPC (Y/N):			ite:			Sto	*N	R2*		
Sequence ID/ Work Center ID)	Operat Descri				Set Up/ Run Hours		Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp		
Draw Nbr		Revision Nb	or :													
D3916		A														
100						0.00								- 4 - 4 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1		
100 Large Fab Large Fab			*** Make li	e with manuel pipine at 9.00" annd i	use jig for o						(10)	me	<u>/3-</u>	07-17		
110		QC6- In:	spect dimension	s to drawing		0.00								DAG		
110 QC Quality Control			Мето			0.00					(D)	13.0	J. 13	(% 89 (00		
4 - 7				•												
120		Identify	as per dwg & St	ock Location:	a004	0.00						,				
120 Packaging Packaging			Memo		Ź	0.00					(10)	27-6	/3	-07-18		

										DQA:	Date:				
NCR: Y	es / No				WORK ORDER NON-C	CON	IFORN	MANCE / UP		QA Closed:	Date:				
<u>.</u>			, *		DISPOSITION	Т	AGAINST DEPARTMENT/PROCESS								
Work Orde	r:				ļ	,				. ,		. —			
Part N	lo	···-			Rework Scrap		ſ	Skid-tube Machining	Crosstube Small Fab		Water Jetd. Eng. Coor.	Engineering Quality			
NCR N	lo		. <u>-</u>		Use-as-is Work Order Update]		noforming Large Fab	Finishing Composite	Rec/Stor	re/Packaging Supplier	Other			
Root				Descri	ption of work order update	lr	nitial	Act	tion	Sign &					
Cause	Date	Step	Qty	(or Non-conformance	Chi	ief Eng	Desc	ription	Date	Verification	QC Inspector			
Doc/Data															
Equip/Tooling															
Operator															
Material															
Setup										l i	1				
Other		l	ļ								:				
Process										i					
Supplier				Į											
Training															
Unapproved		1	<u> </u>	<u> </u>				<u> </u>		<u> </u>					
	<u></u>		,			AUL	T CATE	GORY							
Landii	ng Gear			_	General		. ·			1	_	7,,,,,,,,			
	Bending				Bend	$\boldsymbol{\vdash}$	Grain		-	Ovalized	<u> </u>	Pressure/Forced Temperature/Cure			
	Centre N	ot Conce	ntric to	O/S -	BOM/Route	-	Hardwa			Over/Under		Weld			
	Cracks	1 0 : 1		<i>'</i> ⊢	Broken/Damaged	-	-	ion Incomplete	Na stana	Part Incorred Part Lost/Mi	<u> </u>	Wrong Stock Pulled			
	Crushed/	Crimpea		_	Burrs	-		ions Incomplete/	Unclear	Part Moved	22111B	I wrong stock runed			
	Cuffs			-	Contamination Countersink	\vdash	Mainte Mislabe		<u> </u>	Positioned V	Vrong				
	Heat Tre		Tuba	\vdash	Cut Too Short	\vdash	Misrea		-	Power Loss/		Other			
	Inspection Ripples in		i iube	-	Drill Holes	\vdash	Offset	u	L	1. OMEL FOSSA	Juige	Totalei			
	Torque V		Evtrucia	<u> </u>	Drawing	\vdash		Calibration		***					
	i jiorque v	AUAG2 III	こくい はりり	11 1	lniamiik	l i	LOUR OIL	Canbration							

Out of Sequence

Outside Dimensions

Turning Sequence

Wave/Twist in Tube

Finish Folio

Work Order ID 100440 Page 2 April-22-13 1:40:28 PM Item ID: D3916-5 Accept *N900040100* Setup Start **Revision ID:** Stop Item Name: Light Rib 4/30/13 **Start Qty: 10.00** *10* **Start Date: Cust Item ID:** Required Date: 4/30/13 Req'd Qty: 10.00 *10* **Customer:** Reference: Start Run Date: **Tooling:** Date: **Approvals:** Stop SPC (Y/N): Date: Date: Sequence ID/ Operation Set Up/ Tool ID Tool # Plan Reject Accept Reject Insp. Work Center ID Qty Qty Number Stamp Description Code **Run Hours** 0.00 130 QC21- Final Inspection - Work Order Release MC 13-07-18 MC 13-7-18 *130* QC 0.00

Memo

Quality Control

			,							DQA:	Date	
NCR: Y	es / No		· , *		WORK ORDER NON-	COI	NFORM	MANCE / UP	DATE			
					,					QA Closed:	Date	·
Work Orde	r.				DISPOSITION				AGAINST DE	PARTMENT	/PROCESS	
Part N					Rework Scrap Use-as-is		r	Skid-tube Machining Moforming	Crosstube Small Fab Finishing	ł	Water Jet d. Eng. Coor. re/Packaging	Engineering Quality Other
NCR N	o			·	Work Order Update]		Large Fab	Composite		Supplier	
Root	Data	Char	0.5		ption of work order update or Non-conformance		nitial		tion	Sign & Date	Verification	QC Inspector
Cause	Date	Step	Qty	(or Non-conformance	Ch	ief Eng	Desc	ription	Date	vernication	QC inspector
Doc/Data	_											ļ
Equip/Tooling						1				1		
Operator	-							·				
Material	\dashv											
Setup Other	\dashv		1									
Process												
Supplier	-											
Training	-		,			İ						
Unapproved												
onapproved 1		.1]		AUL	T CATE	GORY		<u> </u>		<u> </u>
Landin	g Gear				General			——,:———··	· · · -			
[Bending				Bend		Grain			Ovalized		Pressure/Forced
	Centre N	lot Conce	ntric to	o/s	BOM/Route	Г	Hardwa	re		Over/Under	tolerance	Temperature/Cure
Ī	Cracks				Broken/Damaged		Inspecti	on Incomplete		Part Incorre	ct	Weld
Ī	Crushed	/Crimped			Burrs		Instruct	ions Incomplete/	Unclear	Part Lost/M	issing	Wrong Stock Pulled
Ì	Cuffs				Contamination		Mainte	enance		Part Moved	•	
	Heat Tre	at			Countersink		Mislabe	eled		Positioned \	V rong	
ľ	Inspecti	on Strip in	Tube		Cut Too Short		Misread	t .		Power Loss,	'Surge	Other

Offset

Out of Calibration

Out of Sequence

Outside Dimensions

Turning Sequence

Wave/Twist in Tube

Ripples in Bend

Torque Waves in Extrusion

Drill Holes

Drawing

Finish

Folio

April-22-13 1:40:28 PM

Work Order ID:

100440

Parent Item:

D3916-5

Parent Item Name:

Light Rib

Start Date: 4/30/13

Required Date: 4/30/13

Start Qty: 10.00

Required Qty: 10.00

Comments:

IPP RevA: new issue DD 09.11.23 verified by:EC 10.03.15 verified by:EC

IPP Rev:B as per dwg revA

•	10.03.13 Verifica b	y.LC											
Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
M3041S0.500W 049 Square Tubing		Purchased	No			100	f	1,065.9843	4.166 	43.852632 -6.666	66	BAL	13-07-17
				Location		Loc Oty	<u>Lo</u>	c Code					
t - 1				WA006		1065.984331							
in 126	080			11846	50	0.00001534							
•	_			12293	38	224.3							
				12356	55	198.684316							
				12506	52	643							

											DQA:	Date	
NCR: Y	⁄es	/ No				WORK ORDER NON-C	100	NFORM	ANCE / UP	DATE			
											QA Closed:	Date:	
Work Orde	عر.					DISPOSITION				AGAINST DE	PARTMENT,	PROCESS	
	- No					Rework Scrap Use-as-is Work Order Update		t Thern	Skid-tube Machining noforming Large Fab	Crosstube Small Fab Finishing Composite	i .	Water Jet d. Eng. Coor. re/Packaging Supplier	Engineering Quality Other
Root						ption of work order update	1	nitial	Ac	tion	Sign &		
Cause		Date '	Step	Qty	٠ ،	or Non-conformance	Ch	ief Eng	Desc	ription	Date	Verification	QC Inspector
Doc/Data Equip/Tooling Operator Material Setup Other Process Supplier Training Unapproved													
							AUL	T CATE	GURY				
Landi		Bending Centre No Cracks Crushed/ Cuffs Heat Trea Inspectio Ripples ir	Crimped it n Strip in i Bend	Tube		General Bend BOM/Route Broken/Damaged Burrs Contamination Countersink Cut Too Short Drill Holes		Instruct Mainte Mislabe Misread Offset	ion Incomplete ions Incomplete/ enance eled	'Unclear	Ovalized Over/Under Part Incorre Part Lost/Mi Part Moved Positioned V Power Loss/	ct ssing Vrong	Pressure/Forced Temperature/Cure Weld Wrong Stock Pulled Other
1		Torque W	/aves in l	Extrusic	n [Drawing	1	Out of	Calibration				


Out of Sequence


Outside Dimensions

Turning Sequence
Wave/Twist in Tube


Finish


Folio





	A MANAGEMENT	de altida					. '	(329)
			-1 46 22					
State to the state of the state	•							1
L							•	* **
		1.00 Miles						
		454						
		1						
								-
	(· ·	P isi						1 1
		19/4/						
			Market Branch				,	
		i.						
		13.60						1
	A. 5	1						
	4,4	1754						
	ings for a							1
	englisher in a graph with the second of the	A Lead						
		1615						1 2
			T-1/2					1
		144	Trans.					1
		4	· Page 1					7/8
	*	*						
		148.415						
		The state of	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1					
		44						
2		10.00						- 2
		i i						
			-12:					1
	1.0	4						
		1. S.						
Ana-		ja,						3
		4	ic in the				1	1
		- 100 pt						1
		Y 2	""""""""""""""""""""""""""""""""""""""					
	4		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1					
		Page.						1
		· Ne						**
d.		94						
		+						
		44.	4 1 2 3 1 1					25
		.U.						
		4						
		1 to 1	1.0					
		-1						
		1.						
		, j., Sa-						1
		4.4						
		197				•		
•	.							Ī
	4.	د. الأنفر	and the second second second				1	
States Call.	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		CONTRACTOR DESCRIPTION OF THE PROPERTY OF THE PARTY OF TH	and the state of t			and the second s	





NOTES:
1) MATERIAL: AISI 304/316 STAINLESS STEEL SQUARE TUBE, 0.50 X 0.50 X 0.049 WALL REF DART SPEC. M304TS0.500W.049
2) FINISH: NONE
3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
4) UNITS: INCHES UNLESS OTHERWISE NOTED
5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX
6) IDENTIFICATION: N/A
7) WEIGHT: 1.07 lbs
9) TUBE FLAT LENGTH 49.5 REF

DESIGN	AJS	DART AEROSPACE	LTD
DRAWN	JPH	HAWKESBURY, ONTARIO, CAI	
CHECKED	0	DRAWING NO.	REV. A
MFG. APPR.	12	[↑] D3916	SHEET 4 OF 4
APPROVED	MA	TITLE	SCALE
DE APPR.	-4	RIB ASSY, 350 BASKET	NTS
DATE 10.0	3.04	COPYRIGHT © 2010 BY DART AEROSPA	RESS CONDITION THAT IS IS

							1
						•	
				κ,			
	4						37
			48-				*
			·				
				•	· • ·		
							-
				,			1
			₹				
							-
							-
	•	;					
			•	•			
	•	·					
		ŧ	•				
			* .				
		· · · · ·					
							. 8
마르크 (1985년 - 1985년 - 1 - 1985년 - 1985		<u></u>	,		••		
물 등 보고 있는 것이 되었다. 그런 그렇게 되었다. 사용		•					
					%.		
						•	·
		A					
			·.				
					·		
	· · · · · · · · · · · · · · · · · · ·			orale.			